

## K00160 ADAPTER KIT Installation Instructions

- 1. The K00160 kit is used for installing a P-0530 ice machine on a Manitowoc 170, 400, 470 and 570, S and C-Series bins.
- 2. Installation (bin must be level before starting):
  - A. Place adapter on bin, as shown. Using the adapter as a template, drill two 5/32" (4 mm.) holes, .500" (12.7 mm.) deep maximum, in the back of the bin. Warning: Do not drill through interior liner. Attach with (2) 10-24 x .500" screws provided.
  - B. Apply foam tape to the edge of the adapter opening as shown in the (A) position. Note: It is recommended to RTV intersections and along front inside edge of foam tape (see drawing) to prevent water tracking.
  - C. Place the ice machine on the adapter. Secure it to the adapter as shown with the (2) machine screws provided.
- 3. Refer to ice machine installation manual for ice machine installation procedures.